Map ID MAP FINDINGS

Direction Distance

Distance EDR ID Number
Elevation Site EDR ID Number
EDR ID Number

Al181 MANHOLE TM1060 NY Spills S104880147
South SURF AV / W 12TH ST N/A

1/4-1/2 0.316 mi.

1667 ft. Site 3 of 8 in cluster Al

BROOKLYN, NY

 Relative:
 SPILLS:

 Higher
 Name:
 MANHOLE TM1060

 Actual:
 Address:
 SURF AV / W 12TH ST

 6 ft.
 City,State,Zip:
 BROOKLYN, NY

 Spill Number/Closed Date:
 0008906 / 2001-05-07

Facility ID: 0008906 Facility Type: ER DER Facility ID: 97182 Site ID: 111091 DEC Region: 2 Spill Cause: Unknown Spill Class: C4 2401 SWIS: Spill Date: 2000-11-01 Investigator: **KMFOLEY** Referred To: Not reported Reported to Dept: 2000-11-01 CID: 312

Water Affected: Not reported Spill Source: Unknown Spill Notifier: Other Cleanup Ceased: Not reported Cleanup Meets Std: False Last Inspection: Not reported Recommended Penalty: False **UST Trust**: False Remediation Phase: 0

Date Entered In Computer: 2000-11-01
Spill Record Last Update: 2001-06-19
Spiller Name: Not reported
Spiller Company: Not reported
Spiller Address: Not reported
Spiller Company: 001
Contact Name: Not reported

DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was

FOLEY DEC INSPECTOR'S NOTES CON ED E2MIS REPORT 11-01-00 2gals. of

unknown oil on 500gals. of water found in TM1060. No sump or sewer connection noticed. Discovered while resampling retro fill for 7B44. Liquid sample taken. Previous records indicate 53ppm. Over 50 tanker will be ordered to pump down on 3-1shift and to mmer with Env. Ops crew. Update 11-01-00 2000hrs. lab Seq300-10440 <1ppm Pressure tested

unit and unit tested good. Oil level also good. Took liquid sample from tansformer. 2330hrs. Cleanup completed as <1ppm, no sump found. 11-02-00 Update Cleanup completed by double washing structure with slix. Liquids were removed by tanker and solids were removed by vactor. No leaking company equipment. Incident closed. Aroclor 1242 1ppm Aroclor 1248 1ppm Aroclor 1254 1ppm Aroclor 1260 1ppm"

Remarks: "ON 500GAL OF WATER - CONTAINED - MANHOLE CONTAINS OIL FILLED

TRANSFORMER - NOT LEAK TESTED AT THIS TIME - CASE #134188 - PRIOR HX

OF TRANSFORMER IS 53PPM OF PCB"

All Materials:

 Site ID:
 111091

 Operable Unit ID:
 829489

Map ID MAP FINDINGS Direction

Distance Elevation Site EDR ID Number Database(s) EPA ID Number

 Operable Unit:
 01

 Material ID:
 546410

 Material Code:
 0066A

Material Name: unknown petroleum
Case No.: Not reported
Material FA: Petroleum
Quantity: 2.00
Units: G
Recovered: .00

Oxygenate: Not reported